

## **HOW TO INSTALL PRINTER/SCANNER DRIVER FOR WINDOWS2000 (FOR MFC730/740) PARALLEL INTERFACE USERS**

---

FOR MFC730/740 PARALLEL USER

**CAUTION! YOU CANNOT INSTALL ONLY TWAIN DRIVER WITHOUT INSTALLING PRINTER DRIVER. PLEASE FOLLOW THIS INSTRUCTION LISTED BELOW FOR INSTALLATION!**

1. Please make a temporary directory on your Hard Disk Drive to save the downloaded self-extracting file.

e.g. C:\730drv

2. Click "DOWNLOAD" to start downloading. To store the downloaded file select the temporary directory you created.

3. Double click on the downloaded self-extracting file. The driver files will be placed in the "C:\7150drv\MFC7150\Win2000\US\_Eng\Setup\Disk1" directory.

4. Connect the MFC to PC by Parallel Cable and restart Windows.

5. Click "Next".

6. Click "Next".

7. Check only "Specify a location" and click "Next".

8. Click "Browse".

9. Click the "MFC730(740)\Win2000\US\_Eng" in your specified directory and Click "Open".

10. Click "OK".

11. Click "Next".

12. The "Digital Signature Not Found" screen appears. Microsoft WHQL "Windows Hardware Quality Lab" provides Digital Signatures for drivers which pass the vigorous tests. Brother is in the process of applying for WHQL certification. To continue Install, click "Yes".

13. Click "Finish".

14. Double click on the downloaded "Setup.exe" file in the specified directory.

e.g. C:\730drv\MFC730(740)\Win2000\US\_Eng\Setup\disk1\Setup.exe

15. Click "Next".

16. Click "Next".

17. Click "Next".

18. If you want to install "True Type compatible fonts", please click "Yes". (If you install "True Type compatible fonts", you can use various fonts when you use MS word etc. There is no problem with installation even if you click "NO".)

19. Click "Next". (When you click "Yes" in the previous step, this screen appears.)

20. Please read the "README" file and close the wordpad application.

21. Click "OK". The Windows2000 driver has been installed.